

# NRC Inspection Closeout Summary

Date: 8/20/2009

Inspection #: <b>2009-003</b>	Inspection Period <b>8/17/09 thru 8/20/09</b>
<b>Inspection Focus:</b> <input type="checkbox"/> Resident Quarterly <input checked="" type="checkbox"/> Special Focus: Configuration Mgmt., Maint. And Surv., Rad Protection for Waste and Transport	
<b>Inspector Finding(s)<sup>1</sup>:</b>	Concise Description
One unresolved item (URI) regarding identifying compensatory measures of the lab sprinkler system during roof repair work.	

<sup>1</sup> Information provided at inspection closeouts is not final, and is subject to modification by the NRC prior to issuance of the Inspection Report. To determine the final disposition of a finding, refer to the Inspection Report by the inspection number given above. Inspection Reports follow closeouts by about 2 to 4 weeks. Information recorded for NFSFacts.com is believed to be accurate at the time of recording by the NFS Licensing Department.